

CORNER RECORD Document Number _____ BURBANK City of -County of Los Angeles, California Brief Legal Description CITY BNDY RIVERSIDE DR. W/O CHAVEZ ST.- MONUMENT PRESERVATION CORNER TYPE **COORDINATES (Optional)** N. Govt. Corner П Control __ NAD27 🗆 NAD83 Meander П Property NAD83 Epoch __ Elev. Rancho Other П X NGVD29 NAVD88 Vert. Datum: Date of Survey May 6, 2003 Metric Imperial Meas. Units: Reestablished Rebuilt 🗷 Established Found & tagged Left as found Corner -Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: see plat: distances measured horizontal; A description of the physical condition of the monument as found and as set or reset: ______ see plat: SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ June 1, 2003 P.L.S. or R.C.E. No. ____ Signed _ COUNTY SURVEYOR'S STATEMENT This Corner Record was received _____

and examined and filed

Signed ______ P.L.S. or R.C.E. No. _____

County Surveyor's Comment